



United States
Department of
Agriculture

Forest
Service

Sawtooth National Forest
Minidoka Ranger District

3650 South Overland Ave.
Burley, ID. 83318-3242
208-678-0430
Fax: 208-677-4878

cc: Lynn

m/003/025

File Code: 2810


Date: November 21, 2005

William Bown
Bonneville Quarries, Inc.
842 West 400 North
West Bountiful, UT 84087

Dear Mr. Bown,

On November 7, 2005, an inspection was conducted on the Lynn Springs Quarry, T.14N., R.16W., Section 29.

The inspector found approximately 1/10 acre of new disturbance at the main quarry. This disturbance was on the Forest Service side of the BLM/FS boundary. The inspector also found two open five-gallon buckets of used oil at the main quarry. Recent excavations on the east side of the quarry has left an overhang of approximately 15 feet that was neither marked nor bermed and is immediately next to an existing road. The access road to the quarry is in poor shape because there are no road drainage structures to control surface water flow down the road nor culverts to allow water to flow under the road. An unauthorized camp area was found to the west of quarry. This camp area consisted of 3 small travel trailers, 5 vehicles and miscellaneous debris and trash.



Used Oil



Pit Wall Overhang

RECEIVED

NOV 23 2005

DIV. OF OIL, GAS & MINING



Caring for the Land and Serving People

Printed on Recycled Paper





Camp Area

Because the camp area is not authorized under your plan of operations we request that it be removed within 2 weeks of the date of this letter. The used motor oil will need to be removed from the site and disposed of properly. Hazardous pit walls should be marked at a minimum to warn the public of the hazard.

Because of the condition of the road, we would like to schedule an on-site visit with you to discuss what type of drainage control structures would be appropriate and their location along the road. Please let us know when you would be available to meet and we will meet with you on-site.

If you have any questions or comments, please contact Steve Flock, Minerals Management Specialist, at the above address or telephone number.

Sincerely,

SCOTT C. NANNENGA
Minidoka District Ranger